

Таблица резьб и подач (метрическая) GH-26XXX ZH

mm/○								mm/○								60 69 56	P	m	DP	n/1"	!	n/1"									
n	t	m	n	t	m	I	II	III	IV	I	II	III	IV	I	II	III	IV	I	II	I	II										
A	A	B	C	D	D	A	A	B	C	D	D																				
0.063	0.09	0.18	0.36	0.71		0.027	0.040	0.076	0.15	0.30		1	1	2	4	8	0.5	1	2	4		1									
0.071	0.10	0.20	0.40	0.80		0.030	0.043	0.085	0.17	0.34		2		2.25	4.5	9		2.25	4.5			2									
0.073		0.21	0.42	0.83		0.031		0.089	0.18	0.35		3										3									
0.079	0.11	0.22	0.44	0.89		0.033	0.047	0.095	0.19	0.38		4	1.25	2.5	5	10	1.25	2.5	5			4									
0.081		0.23	0.46	0.92		0.034				0.39		5						56	28	14	7	28	14	7	3½	5					
0.084	0.12	0.24	0.48	0.95		0.036	0.050	0.101	0.20	0.40		6										27	13½		6						
0.087		0.25	0.49	0.98		0.037	0.052	0.104	0.21	0.42		7		2.75	5.5	11		2.75	5.5						7						
	0.13	0.27	0.53	1.07	1.68		0.057	0.114	0.23	0.46	0.72		8	1.5	3	6	12	0.75	1.5	3	6	48	24	12	6	24	12	6	3	8	
	0.16	0.29	0.58	1.17	1.84		0.062	0.124	0.24	0.49	0.78		9										44	22	11	5½	22	11	5½	2¾	9
	0.15	0.30	0.60	1.21	1.89		0.064	0.128	0.25	0.51	0.80		10																10		
	0.31	0.62	1.25	1.96		0.066	0.133	0.26	0.53	0.83		11	1.75	3.5	7	14	1.75	3.5	7									11			
	0.16	0.32	0.64	1.29	2.02		0.068	0.137	0.27	0.55	0.86		12										40	20	10	5	20	10	5	2½	12
	0.17	0.34	0.68	1.38	2.16		0.073	0.146	0.29	0.58	0.92		13																13		
			1.45	2.24					0.60	0.95		14							36	18	9	4½	18	9	4½	2¼	14				
			1.61	2.52					0.68	1.07		15							32	16	8	4	16	8	4	2	15				

Таблица резьб и подач (дюймовая) GH-26XXX ZH

— X0.1in/O								X0.1in/O								82 97		P		$\frac{m}{n}$		DP		$n/1''$!		$n/1''$													
n	t	m	n	t	m	A	A	B	C	D	D	A	A	B	C	D	D	I	II	III	IV	I	II	III	IV	I	II	III	IV	I	II	I	II								
0.023	0.033	0.067	0.134	0.264		0.010	0.015	0.029	0.057	0.113							82 97	81	1	1	2	4	8	0.5	1	2	4			1											
0.026	0.037	0.074	0.169	0.298		0.011	0.016	0.032	0.064	0.128									2		2.25	4.5	9			2.25	4.5			2											
0.027		0.078	0.156	0.309		0.012		0.034	0.068	0.132									3											3											
0.029	0.061	0.082	0.166	0.331		0.018	0.036	0.072	0.143										4	1.25	2.5	5	10		1.25	2.5	5			4											
0.030		0.086	0.171	0.342		0.013				0.147									5											5											
0.031	0.045	0.089	0.179	0.353		0.019	0.038	0.076	0.151										6											6	19	9 $\frac{1}{2}$	23	11 $\frac{1}{2}$							
0.032		0.093	0.183	0.365		0.016	0.020	0.039	0.079	0.159									7		2.75	5.5	11			2.75	5.5				7										
	0.048	0.108	0.197	0.398	0.625		0.022	0.043	0.087	0.174	0.272								8	1.5	3	6	12	0.75	1.5	3	6	48	24	12	6	24	12	6	3	8					
	0.052	0.108	0.215	0.435	0.684		0.023	0.047	0.091	0.185	0.295								9									44	22	11	5 $\frac{1}{2}$	22	11	5 $\frac{1}{2}$	2 $\frac{3}{4}$	9					
	0.056	0.112	0.223	0.450	0.783		0.024	0.048	0.095	0.192	0.302								10												10										
	0.115	0.230	0.465	0.729		0.025	0.050	0.098	0.200	0.314									11	1.75	3.5	7	14		1.75	3.5	7						11								
	0.063	0.119	0.238	0.480	0.751		0.026	0.052	0.102	0.208	0.325								12									40	20	10	5	20	10	5	2 $\frac{1}{2}$	12					
	0.063	0.126	0.252	0.513	0.804		0.028	0.055	0.109	0.219	0.348								13									36	18	9	4 $\frac{1}{2}$	18	9	4 $\frac{1}{2}$	2 $\frac{1}{4}$	13					
			0.531	0.833					0.227	0.359	14																														
			0.599	0.937					0.257	0.404	15																														

82
97
57
69